

**SHOPMASTER
GUNMASTER
MANUAL**

COPYRIGHT SHOPMASTER 1981-2015

content

1. SPECIFICATION	1
2. APPLICATION	1
3. CONSTRUCTION	1
4. ELECTRICAL SYSTEM	2
5. GENERAL DIMENSION	4
6. INSTALLATION	5
7. LUBRICATION	7
8. OPERATING INSTRUCTION	8
9. CHECKING PROBLEMS AND REPAIR	12
10. MAINTENANCE	12
11. STANDARD ACCESSORIES	14
12. OPTIONAL ACCESSORIES	15

1. SPECIFICATION

1.1 TURNING

Distance between centers	300mm
Swing over bed	420mm
Max longitudinal travel	460mm
Max cross travel	200mm
Spindle taper	M.T.4
Travel of tail stock barrel	75 mm
Taper of tail stock barrel	M.T.3
Spindle hole diameter	Φ28mm
Spindle speed	7 steps 160-1360r.p.m.
Longitudinal lead screw threads can be cut	6T.P.I./4mm
Inch thread can be cut	4-120T.P.I./0.2-6mm
Range of automatic feeding	0.002-0.014inch/0.05-0.35mm

1.2 DRILLING & MILLING

Spindle taper	M.T.3
Spindle travel	110mm
Max distance between spindle center and column	285mm
Max distance between nose and table	306mm
Spindle speed	16 steps 120-3000r.p.m.
Table size	475 X 160mm
Drilling capacity	Φ22mm
End milling capacity	Φ 28mm
Diameter of milling cutter holder	Φ 80mm

1.3 OTHERS

Main motor power	0.55Kw
Motor of drill and mill unit	0.55Kw
Voltage	As customer's requirement
Frequency	As customer's requirement
Net weight	230Kg
Gross weight	275Kg
Overall dimension	1270 X 610 X 955mm
Packing size	1130 X 590 X 1110mm

2. APPLICATION

The machine has the functions of turning, milling, drilling and thread cutting. Feed can be controlled automatically and manually, suitable for processing metal, wood and other materials. It is extensively used in job-shops, teaching, scientific research, occupation training, especially in house for repairing household utensils.

3. CONSTRUCTION

The machine consists of bed, headstock, drilling and milling unit, work table, tailstock, motor, etc. The functions of turning, drilling and milling can be made in one machine. Worktable feed can be controlled automatically and manually in longitudinal and cross direction. The drilling-milling head can rotate 180

was designed according to CE standard and very safe. It also can be controlled by personal computer when connecting with it.


4.ELECTRICAL SYSTEM


4.1 COMPOSITION

The system consists of alternating current contactor(-K), red emergency button(-S1), green(-S2), pilot(-HL), microswitch(-S3,-S4,-S5), shift switch, etc. The system has the protection of lose-voltage, and cutting off the current when cover is opened.

4.2 OPERATION

According to the manual, after finish all the preparations, close all the protection instrument, let the red button in original condition. Push the green button, now pilot light which show that alternating contactor has put through the main circuit and the machine enter into working condition. Push the red emergency button, the alternating contactor break down . Now whether the spindle motor or drilling-milling motors are all cut off. When working, if the protection instrument doors are opened the motors also are cut off.





SINGLE PHASE 110V/220V/240V CIRCUIT




4.3 CAUTION

- (1) A FUSE AS THE FOLLOWING CHART SPECIFICATIONS MUST BE CONNECTED BETWEEN CURRENT AND THE MACHINE.
- (2) THE GROUND TERMINAL OF THE MACHINE MUST BE GROUNDED PERFECTLY.
- (3) BEFORE CUTTING OFF CURRENT OF THE MACHINE, DON'T OPEN ELECTRIC PROTECTIONS. IF SOMETHING IS WRONG WITH THE ELECTRICAL SYSTEM, PLEASE ASK FOR A REPAIRMAN TO HELP YOU.

CHART 4.1 SPECIFICATION OF FUSE

PHASE VOLTAGE	SINGLE PHASE	THREE PHASE
110V	30A	
220V	20A	10A
380V		7.5A

5. GENERAL DIMENSION



6. INSTALLATION


6.1 FOUNDATION

The base of the machine foundation must be solid without noticeable deflection and heavy enough to support the weight of the machine. The floor installation must be fairly level.

If you use our stand, please place the stand in installation position, then make mark in installation hole position, then move the stand, drill hole in the marks to make them fit for the foundation bolts. Cover the foundation bolts, place two adjustable iron spacer in the end of headstock and tailstock separately. In order to increase the touched square, please stagger the front and back iron spacer. Hereafter, place the stand on the adjustable iron spacers and fix with foundation bolts. Lift the machine on the stand and fix to stand by using the nut and bolts.

6.2 INSTALLATION OF DRILLING AND MILLING HEAD


Firstly, clean turning part and connected part of drilling-milling stock and turning part. As the following figure, place the drilling-milling head on the turning part, then fit brake nut, lever, cork, etc.



6.3 LIFTING

According to the figure, lift the machine, place spacers on the machine in order to prevent its surfaces being damaged. When lifting, in order to avoid the


position and lock the slide. Place the machine carefully on the base, you can adjust the machine position by iron edge, plug gauge. Finally fit the machine perfectly.




Lubrication Chart:

Item	Name	Location	Method	Lubrication	How Often
1	Head Stock	Gear Bearing	Oil Splash	Machine Oil	Daily
2	Tool Post	Screw Rod	Oil Gun	Machine Oil	Daily
3	Hanging Wheel Box	Hanging Wheel	Oil Gun	Machine Oil	Daily
4	Tailstock	Screw Rod Barrel	Oil Gun	Machine Oil	Daily
5	Lead Screw	Screw	Oil Gun	Machine Oil	Daily
6	Trailer	Cross Feed Screw	Oil Gun	Machine Oil	Daily
7	Drill/mill Headstock	Worm Gear	Oil Gun	Machine Oil	Daily

Figure 7



8. OPERATION EXPLANATION



(1) Lead screw clutch lever	(16) Tool post feed hand wheel
(2) Shift switch	(17) Slide lock lever
(3) Change lever	(18) Cross feed clutch lever
(4) Start switch	(19) Longitudinal feed hand wheel
(5) Drilling - milling stock lock lever	(20) Cross feed hand wheel
(6) Drilling - milling shift switch	(21) Saddle lock lever
(7) Drilling - milling belt lock lever	(22) Half nuts lever
(8) Drilling - milling micro feed lever	(23) Pilot
(9) Drilling - milling micro feed clutch lever	(24) Master switch/Emergency switch
(10) Drilling - milling spindle feed lever	(25) Returning screw
(11) Drilling - milling spindle lock lever	(26) Main spindle pulley lock lever
(12) Tail stock barrel lock lever	(27) Rack
(13) Tail stock hand wheel	(28) Ball crank lever
(14) Screw	(29) Tool post lock lever
(15) Tail stock lock lever	

8.1 CAUTION

- a BEFORE FAMILIAR WITH THE CONTROL PARTS AND THEIR FUNCTIONS, PLEASE DON'T OPERATE THE MACHINE COMPLETELY.
- b CHECK LUBRICATING SURFACES AND SLIDES, TURNING SPARE PARTS REFERING TO LUBRICATING CHART AND USE GREASE TO LUBRICATE.
- c AFTER WORKING, YOU SHOLD CUT OFF CURRENT.
- d THE MACHINE IS NOT ARMED WITH LIGHT EQUIPMENT. YOU SHOULD SUPPLY ENOUGH LIGHT INSTRUMENT YOUSELF, AND AVOID SHADOW INTERRUPTING IN ORDER TO PREVENT THE DANGER HAPPENING BECAUSE OF LACK LIGHTING.
- e KEEP CLAMPING THE WORKING PIECE FIRMLY, PREVENT IT FLYING OFF. THE OUTSTANDING PART OF THE PIECE SHOULD NOT BE MORE 80MM. THE RATE OF TH OUTSTANDING PART AND DIAMETER SHOULD BE NOT MORE THAN 4.

STOP.

g WHEN NEEDING TO ADJUST TOOL, THE MACHINE OR WORKING PIECE, YOU PUSH STOP BUTTON TO MAKE THE MACHINE STOP.

8.2 MAIN SPINDLE DRIVING

a Before starting the machine, you should check the tension of belt. The belt should depress about 1/2 inch under normal finger pressure. Too tension of V belt will ruin bearings. The tension of the belts can be adjusted by lever(26).

b Main spindle running, stop, forward and reserve can be realized by shift switch(2). If needing to change main spindle running, please turn the shift switch to middle position, after a moment, then to the opposite side. Or, if turn the lever to another side directly, the direction of main spindle running don't change.

c Loose lever(26), change the belt position in tower pulley, then tighten belt. Now the main spindle can obtain 7 kinds of speed according to the following chart.

THE SPINDLE SPEEDS (○/min)

A-F	A-E	A-D	B-F	C-F	B-E	C-D
160	300	375	470	600	870	1360

8.3 DRILLING-MILLING SPINDEL DRIVING

a At first check the protection instrument if effective, then push master switch, pilot light, the machine is awaiting working. Now stop, forward and reserve of drilling-milling spindle can be make by operating the shift switch.

b Drilling-milling spindle feeding can be changed by lever(10), If need micro feeding, pull out drilling-milling clutch lever(9), then operate lever(8) to micro feed.

c The speed of drilling-milling spindle can be made by lever(7):push lever to backward, loose belt, change the belt position on the tower pulley, then push the lever to the front to tighten belt, finally lock lever(7), 16 kinds of speed can be obtained as the following chart.


THE DRILLING-MILLING UNIT SPEEDS (○/min)

-A	-B	-A	-C	-A	-D	-B	-A
E-	E-	D-	E-	C-	E-	D-	B-
120	200	310	350	400	450	530	600
-B	-C	-B	-D	-C	-D	-C	-D
C-	D-	A-	C-	B-	B-	A-	A-
660	900	1380	1450	1670	2140	2350	3200


8.4 LONGITUDINAL FEED

a HAND FEEDING: lever(1) in left position, half – nut lever(22) in original position, turn the hand wheel(19), now longitudinal hand feeding can be made.

b AUTOMATIC FEEDING: lever(1) in right position, half – nut lever(22) in clutch position, now cross feeding can be made. By changing lever(3) position and gear A B C D, 12 kinds of automatic feeding amount can be obtained as follows. (The left chart is for the inch leadscrew, and the right chart is for the metric leadscrew)



A	24	30	36	42	
mm	I	0.2	0.25	0.30	0.35
	II	0.1	0.125	0.15	0.175
	III	0.05	0.063	0.075	0.088
INCH	I	0.008	0.010	0.012	0.014
	II	0.004	0.005	0.006	0.007
	III	0.002	0.0025	0.003	0.0035



A	24	30	36	42	
mm	I	0.2	0.25	0.30	0.35
	II	0.1	0.125	0.15	0.175
	III	0.05	0.063	0.075	0.088
INCH	I	0.008	0.010	0.012	0.014
	II	0.004	0.005	0.006	0.007
	III	0.002	0.0025	0.003	0.0035


8.5 CROSS FEEDING

a Hand feeding can be made by operating the lever(20) directly.


b Automatic feeding: Lever(1) in right position, half – nut lever(22) in original position. Pull out cross feed clutch lever(18), now cross automatic feeding can go. By changing the gear A B C D, 12 kinds automatic feeding amount can be obtained.

8.6 THREE CUTTING

a Main spindle in low speed, lever(1) in right position, half – nut lever(22) make half – nuts clutch. Now can go to cut thread. Different thread pitch (inch, metric) cutting can go by changing the lever (3) and gear A B C D. (The right chart is for the inch leadscrew, and the left chart is for the metric leadscrew)



A	24	27	30	33	36	39	42	48	60
mm	I	4	4.5	5	/	6	/	7	8 10
	II	8	9	10	11	12	13	14	16 20
	III	16	18	20	22	24	26	28	32 40
INCH	I	/	/	/	/	18	/	/	24 30
	II	/	27	30	33	36	39	42	48 60
	III	/	54	60	66	72	78	84	96 120
mm	A	36	42	48	60	72			
	II	0.75	/	1	1.25	1.5			
	I	1.5	1.75	2	2.5	3			
mm	I	3	3.5	4	5	6			



A	24	27	30	33	36	39	42	48	60
INCH	I	4	4.5	5	/	6	/	7	8 10
	II	8	9	10	11	12	13	14	16 20
	III	16	18	20	22	24	26	28	32 40
INCH	I	/	/	/	/	18	/	/	24 30
	II	/	27	30	33	36	39	42	48 60
	III	/	54	60	66	72	78	84	96 120
mm	A	24	27	30	36	42	48	60	72
	I	0.8	/	/	/	/	/	/	/
	II	0.4	0.45	0.50	0.60	0.70	0.8	/	/
mm	I	/	/	2.5	3	3.5	4	5	6
	II	/	/	1.25	1.5	1.75	2	2.5	3
	III	/	/	0.75	/	1	1.25	1.5	

b CAUTION: IN CUTTING THREAD COURSE, DON'T LEAVE LEVER(1) OFF RIGHT POSITION. WHEN A KIND OF THREAD NEED MANY TIMES

WORKING PIECE. OPERATE THE SHIFT SWITCH(2) TO MAKE MOTOR RUN IN THE OPPOSITE DIRECTION. AFTER FINISHING RETURNING TOOL CONTINUE TO CUT THREADS. DO SO MANY TIMES UP TO FINISHING CUTTING THREADS.

8.7 TAIL STOCK

The tail stock can slides along the bed ways freely and can be locked in any position by the lock lever(15).

Tail stock barrel position can be adjusted by turning the tail stock hand wheel(13), locked by lock lever(12). Before shipment, it is sure that the tail stock center and spindle center are in the same line. If need to use the tail stock center to cut small taper, you should loose the screw(14), adjust the two returning screw(25) to make the deviation between spindle center and tail stock center. Now you can start the work. After finishing proceeding, you should do as the above to move tail stock in original position. When use tail stock to do the external cutting and get a taper, please adjust the returning screw(25) as the above way. Now you can eliminate the taper.

8.8 THREADING DIAL

Threading dial performs the function of indicating the proper time to engage the half-nut so that the tool will enter the same groove of the thread on each successive cutting. Threading dial is marked with lines numbered 1. 2. 3. 4. 5. 6, and a single line is marked on the housing of the threading dial (fixed line).

The instruction plate (see the following figure) riveted on the threading dial shows the selection of matching the revolving lines with the fixed line.

When cutting thread, engage the half-nuts at the proper numbers shown on the scale column of the threading dial plate. 1-6 on the scale means the half-nuts can be engage on any of the numbered lines 1.2.3.4.5.6. In the first cutting, if engage the half-nuts when matching the numbered lines with fixed line, you can engage the half-nuts for successive cutting only when matching the numbered lines with the fixed line. 1.4 mean that the half-nuts can be engaged on 1.2 for successive cutting. If the half-nuts engage with the lead screw all the time while cutting the thread, need not to use the threading dial. In this case, after finishing each successive cutting, firstly back the tool and reverse the motor, then move the tool to the last start cutting position and make the next successive cutting.

INDICATOR TABLE							
TPI	SCALE	TPI	SCALE	TPI	SCALE	TPI	SCALE
8	14	12	1-6	20	14	32	14
9	1-6	14	14	22	14	40	14
10	14	16	14	24	1-6		
11	14	18	1-6	28	14		

9. CHECK PROBLEMS AND REPAIRING

CAUTION: BEFORE CHECKING, PLEASE TURN OFF THE CURRENT.

9.1 Turn on the current, the spindle doesn't run.

a The voltage is not right and the main switch turned off-----please adjust the input voltage and turn on the main switch.

b The fuse in electric box has broken-----please change a new one.

c Wire connector is loosening-----please check and fix it again.

9.2 The motor is too hot or not powerful

a Overloading or working time is too long-----please reduce it.

b The voltage is too low-----adjust to correct voltage.

c Poor quality of motor----please change a new one.

d The fuse or wire connector is not good (easily make the motor short circuit---please turn off the current and change a fuse.

e The belt is too tight----please loose it to suitable position.

9.3 Temperature of main spindle bearings is too high.

a Has not enough grease to lubricate----please fill the oil according to oil gauge.

b The bearing assembly is too tight-----normally, run the spindle by hand easily, otherwise, adjust the spindle back nut.

c High speed turning for long time----slightly reduce the cutting amount.

9.4 Shortage of motive force when the spindle is running.

a The belt is too loose or worn and tore----please adjust the belt tension to correct position or change a new one.

b The motor is burnt---please change a new one.

c The fuse has broken---please change a new one.

9.5 Making small taper when external turning.

a It is not on the same line between the spindle center and the tail stock center---please adjust the tail stock according to the operation manual.

b The moving line of carriage doesn't parallel to the spindle center---please loose the lock screw of head stock and adjust the spindle center to requirement and lock.

9.6 During proceeding, the surface of work piece is very rough.

a The space of the spindle bearing is too big---adjust it to correct position or change a new one.

b The space between the saddle and the gib is too big---adjust them to correct position.

c The tool is not sharp---please sharpen it.

d The work piece doesn't lock tightly---please lock it tightly.

e The precision of spindle bearing is too bad to wear-----please change a new one.

10. MAINTENANCE

Please often keep the machine in good condition and good precision. It is advisable that maintenance is better than repair.

10.1 DAYLY MAINTENANCE

- a Before using everyday, please pour the oil and lubricate all the moving parts.
- b If the spindle temperature is too high or too noisy, please stop the machine and check it in order to keep its precision.
- c When the machine is in trouble, please stop to repair it. If you don't do it well, please ask for the local repairman or supplier to help you.
- d. It is not allowable to work the machine with too many loads.
- c Before leaving the workshop, please clean the working area, unload the work piece, turn off the power, be careful to clean the iron chipping and shavings and dust, pour into the lubricating oil or antirust oil according to the manual.

10.2 Weekly maintenance

- a Clean and protect the screw.
- b Check all sliding turning surfaces if lack of lubricating, if not, please pour into oil.

10.3 Monthly maintenance

- a Adjust all the gib space of the saddle.
- b Lubricate the worm gear, half nut bearings in order to prevent wearing.

11. STANDARD ACCESSORIES


Item no.	Item name	Specification	Quantity	Remarks
1	3-jaw chuck	130mm	1	Installed
2	Dead centers	M3	1	
		M4	1	
3	Wedge		1	
4	Tie rod		1	Installed
5	Tie rod washer		1	Installed
6	Tool post wrench		1	
7	Double end wrench	13x16mm	1	
8	Allen wrench	3mm	1	
		4mm	1	
		5mm	1	
		6mm	1	
		8mm	1	
9	"-" screw driver	100x6mm	1	
10	Double gears(m-1)	60/120 gear	1	60/127 inch
		120/127 gear	1	(metric, inch)
	Gear(m-1)	24 gear	1	(metric, inch)
		27 gear	1	(metric, inch)
		30 gear	1	(metric, inch)
		33 gear	1	(metric, inch)
		36 gear	1	(metric, inch)
		42 gear	1	(metric, inch)
		48 gear	1	(metric, inch)
		60 gear	1	(metric, inch)
		72 gear	1	(metric, inch)
		120 gear	1	(metric, inch)
		39 gear	1	inch

The descriptions and specifications given in the manual are subject to alteration without notice.


12 OPTIONAL ACCESSORIES (ACCORDING TO THE SUPPLY CONTACT)


Item no.	Item name	Specification	Quantity	Remarks
1	Lathe tool		1	
2	Milling cutter holder		1	
3	Reversible thread tapping tools		1	
4	D.C. motor system		1	
5	Machine stand		1	
6	Protection for chuck		1	
7	Protection for lead screw		1	
8	Protection for tool post		1	
9	Protection for drilling and milling		1	
10	Drill chuck	1-13mm	1	
11	Follow rest		1	
12	Steady rest		1	


12.
13







617





















Faint, illegible handwritten text or markings, possibly a signature or date, located in the upper middle section of the page.

























T 506



214	key 4×10	255	hole plug
215	gear	256	hole plug
216	hex nut M10	257	shaft C
217	roll pin(3×8)	258	shaft B
218	roll pin(4×20)	259	brass bushing
219	flat point set screw M5×20	260	oil glass
220	hex nut M5	261	fork
221	pan head screw M5×12	262	spacer(12
222	gear C	263	fork arm
223	gear C(2)	264	straight pin(B12×45
224	gear C(1)	265	handle knob M10×32
225	brass bushing	266	spacer
226	cover	267	handle
227	taper roller bearing 2007108(40×(68×18	268	handle seat
228	gasket(left)	269	steel ball φ6.5
229	duplex gear(B)	270	spring φ5×0.8×15
230	brass bushing	271	flat point set screw M8×5
231	cover(left)	272	roll pin φ4×25
232	hex socket head cap screw M5×6	273	roll pin φ5×18
233	spacer		
234	V—belt Z710	301	connection tube φ10
235	pulley	302	round phillips screw M4×16
236	spanner nut M40×1.5	303	round phillips screw M4×8
237	locking washer φ40	304	electric box
238	pulley spacer	305	hex socket head cap screw M6×10
239	external snap ring φ63	306	electric housing
240	key 10×25	307	pulley box
241	hex socket cap screw M5×12	308	micro switch LX5—11N
242	bracing plate	309	connection tube
243	oil plug	310	pan slotted screw M4×25
244	O ring	311	electrical panel
245	spindle	312	relay B16
246	hex head bolt M8×25	313A	killoff switch LAY3
247	key 8×22	314A	start switch LA19
248	flange	315	wire block
249	gasket(right)	316	pan phillips screw M4×10
250	taper roller bearing 2007109 φ45 φ75×19	317	light indicator AD11
251	locking ring	318	on—off switch H25—10
252	gear A	319	electrical plate
253	cone point set screw M8×10	320	pan phillips screw M4×10
254	key 5×14	321	pivot

322	straight pin $\varphi A2 \times 12$	514	frame cover
323	spring $9 \times 0.8 \times 50$	515	eccentric flange
324	hex nut M4	516	hex socket head cap screw $M6 \times 20$
325	roll pin $\varphi 3 \times 14$	517	cone point set screw $M8 \times 12$
326	latch piece	518	motor pulley
327	flat head phillips $M4 \times 16$	519	pan phillips screw $M4 \times 6$
328	micro switch lever	520	see-through window
329	hex nut M5	521	mill-drill cover (upper)
330	door	522	pulley seat flange
331	round head screw $M5 \times 35$	523	hex socket head cap screw $M6 \times 40$
332	stud	524	taper pin $\varphi A5 \times 45$
333	knob $A8 \times 32$	525	ball bearing $108\varphi 40 \times \varphi 68 \times 15$
318D	on-off plate	526	external snap ring $\varphi 40$
318E	switch knob	527	V-belt Z860
318C	switch seat	528	mill-drill pulley
318B	flat head screw $M3 \times 15$	529	knob $CM8 \times 25$
318F	pan head screw $M2 \times 12$	530	cap
401	idle pulley	531	pan nhillips screw $M5 \times 10$
402	ball bearing $104\varphi 20 \times \varphi 42 \times 12$	532	mill-drill cover post
403	spacer	533	post insert
404	shaft	534	micro switch LX5-11H
405	washer	535	brake spacer
406	flat slotted screw $M5 \times 10$	536	stud $AM10 \times 60$
407	cover	537	handle $BM10 \times 80$
408	washer $\varphi 12$	538	dog point set screw $M8 \times 14$
409	handle	539	flat point set screw $M8 \times 12$
501	V-belt Z800	540	cone point set screw $M8 \times 20$
502	hex socket head cap screw $M10 \times 40$	541	hole plug
503	mill-drill head	542	cone point set screw $M8 \times 12$
504	mill-drill head support column	543	mill-drill cover (lower)
505	brake pad (pair)	544	washer $\varphi 6$
506	brake spacer	545	pan head screw $M6 \times 12$
507	stud $AM10 \times 80$	546	motor mount
508	handle seat	547	hex head bolt $M10 \times 30$
509	handle	548	mill-drill cover post
510	handle knob $BM10 \times 80$	549	connectoin tube ($M162$ pcs, $M181$ pc)
511D	on-off switch plate	550	motor (same as # 111)
512	switch plate	551	key $A5 \times 16$
513	flat slotted screw $M5 \times 8$	552	tension handle
		553	pan head screw $M6 \times 20$
		554	eccentric shaft

- | | | | |
|------|---|-----|---|
| 555 | idle pulley | 622 | crank |
| 556 | ball bearing 104 ϕ 20 \times ϕ 42 \times 12 | 623 | roll pin ϕ 4 \times 14 |
| 557 | spacer | 624 | handle M8 \times 40 |
| 558 | external snap ring ϕ 42 | 625 | roll pin ϕ 5 \times 35 |
| 559 | bearing cover | 626 | oiler ϕ 6 |
| 560 | flat head srew M5 \times 10 | 627 | spring housing cover |
| 561 | quill | 628 | spring housing |
| 562 | gasket | 701 | hex socket head cap screw M6 \times 20 |
| 563 | ball bearing 2007107 ϕ 35 \times ϕ 62 \times 17 | 702 | straight pin A ϕ 5 \times 25 |
| 564 | spline spindle | 703 | trestle B |
| 565 | cover | 704 | table |
| 566 | cone point set screw M5 \times 6 | 705 | oilet ϕ 6 |
| 567 | bearing 2007106 ϕ 30 \times ϕ 55 \times 16 | 706 | trestle A |
| 568 | spanner nut M30 \times 1.5 | 707 | locking screw |
| 569 | washer ϕ 30 | 708 | locking lever |
| 511E | on—off switch | 709 | roll pin ϕ 2 \times 10 |
| 511F | pan head screw M2 \times 12 | 710 | hex head bolt M4 \times 12 |
| 511A | switch, mill motor | 711 | handle M6 \times 50 |
| 511B | switch seat | 712 | washer |
| 511C | flat head screw M3 \times 15 | 713 | handwheel B12 \times 100 |
| 601 | quill feeding box | 714 | dial seat A |
| 602 | gear shaft | 715 | spring piece |
| 603 | key 6 \times 14 | 716 | dial |
| 604 | cone pointset screw M6 \times 8 | 717 | fixing sleeve A |
| 605 | worm gear | 718 | spanner nut M14 \times 1.5 |
| 606 | clutch jaw | 719 | ball bearing 8102 ϕ 15 \times ϕ 28 \times 9 |
| 607 | taper pin ϕ D5 \times 28 | 720 | spacer A |
| 608 | stud | 721 | gear |
| 609 | dial | 722 | key 4 \times 18 |
| 610 | spring piece | 723 | T—key |
| 611 | dial seat | 724 | cross feed screw |
| 612 | handle | 725 | cross feed nut |
| 613 | handle knob BM8 \times 40 | 726 | adjust screw |
| 614 | cone point set screw M6 \times 18 | 727 | table gib |
| 615 | knurled knob BM10 \times 40 | 728 | carriage gib |
| 616 | worm | 729 | cone point set screw M6 \times 8 |
| 617 | dial seat | 730 | taper pin 5 \times 25 |
| 618 | spring | 731 | carriage |
| 619 | screw M5 \times 25 | 732 | cone point set screw M8 \times 16 |
| 620 | worm shaft | 733 | flat point set screw M8 \times 12 |
| 621 | roll pin ϕ 4 \times 20 | 734 | pin |

735	locking stud	802	hex socket head screw M8×20
736	handle knob M6×20	803	step motor
737	handle M6×32	804	hex socket head screw M5×15
738	flat point set screw M8×8	805	small timing pulley
739	spring φ6	806	large timing pulley
740	steel ball φ6.5	807	timing belt
741	handle seat	808	hex socket set screw M5×16
742	handle BM6×50	809	hex socket set screw M5×12
743	eccentric wheel	810	cover (X)
744	roll pin φ4×30	811	pan phillips screw M4×8
745	arm	812	step motor bracket (Y) (transversal)
746	half nut seat	813	spacer
747	stop pin	814	straight pin φ5×12
748	half nut	815	shaft
749	spacer E	816	straight pin φ4×12
750	spacer B	817	timing belt 100X1.037
751	gear	818	motor mount
752	roll pin φ4×22	819	cover (Y)
753	spacer C	820	step motor bracket (Z) (vertical)
754	shaft pinion	821	spacer
755	dial	822	timing belt
756	fixing sleeve B	823	cover (Z)
757	shaft		
758	key 5×8	901	tailstock
759	gear	902	T-key
760	apron	903	tailstock nut
761	cone point set screw M8×16	904	tailstock barrel
762	spacer D	905	set screw M4×8
763	bevel gear	906	tailstock screw
764	pan phillips screw M6×8	907	key C4×18
765	washer φ6	908	spacer
766	pull-push knob	909	straight pin D φ5×8
767	washer φ12	910	nut seat
768	gear	911	hex socket head screw M5×20
769	shaft	912	dial
770	dial seat B	913	dial seat
771	brass bushing	914	spring piece
772	shaft	915	handwheel B12×100
773	gear	916	washer φ10
774	spacer 12	917	acorn nut M10
775	brass bushing	918	handle M6×50
776	spacer 26	919	locking pad (lower)
777	washer	920	locking pad (upper)
801	step motor bracket(X) (longitudinal)	921	stud AM10×40

922	locking spacer	T401	hex nut
923	handle seat	T402	micro switch
924	handle	T403	pan head screw
925	handle knob M10×32	T404	cover support
926	oiler φ6	T405	hex socket cap screw
927	set screw M10×50	T406	support arbor
928	key	T407	pan head screw
929	set screw M5×12	T408	stell ball φ6.5
930	washer φ10	T409	spring 0.8×5×14
931	hex head bolt M10×40	T410	flat set screw
T101	box	T411	hex nut
T102	cover arbor	T412	set screw
T103	pan slotted screw	T413	connection tube
T104	sleeve	T414	cover
T105	set screw	T501	steady rest center frame
T106	switch	T502	steady rest center frame head
T107	pan slotted screw	T503	small knob
T108	spring	T504	washer(8
T109	screw	T505	locking bolt
T110	cover	T506	cotter pin(6×20
T111	hex socket cap screw M6×30	T507	washer(6
T201	threading dial seat	T508	locking pin
T202	shaft	T509	brass head
T203	indicator plate	T510	finger sleeve
T204	pan phillips screw M4×12	T511	adjusting bolt
T205	gear	T512	large knob
T206	set screw M5×8	T513	roll pin(3×16
T207	revet φ2×4	T514	slotted set screw,dog point,M6×16
T208	hex socket head screw M6×12	T515	hex nut M6
T209	threading dial plate	T516	hex socket head screw M10×35
T301	cover mount(left)	T517	washer(10
T302	flat slotted screw M4×10	T518	chock
T303	leadscrew cover(left)	T519	knurled screw
T304	cover seat(left)	T601	large knob
T305	hex socket head screw M6×12	T602	roll pin M3×16
T306	cover seat(right)	T603	adjusting bolt
T307	cover mount(right)	T604	finger sleeve
		T605	brass head
		T606	follow rest frame

T607	set screw dog point set screw M6×16	T719	oiler
T608	hex nut M6	T720	screw
T609	knurled screw	T721	pin
T701	nut M10	T722	screw TR12
T702	washer 10	T723	nut TR12
T703	T-belt M10×30	T724	angle rule
T704	screw M4×12	T725	mobile jaw
T705	key	T726	set pin
T706	base	T727	hex socket head screw (M5×8)
T707	screw	T728	set screw
T708	rubber	T729	gib
T709	vice	T730	bolt M10×100
T710	jaw washer	T731	tool base
T711	hex socket head screw	T732	spring $\phi 5 \times 0.6 \times 30$
T712	handle B8×25	T733	positioner
T713	pin $\phi 3 \times 16$	T734	tool post
T714	nut M10×1	T735	screw M8×25
T715	dial seat	T736	set washer
T716	spring piece	T737	nut M10
T717	dial	T738	handle
T718	screw seat	T739	handle knob M10×32